Copy of iDX CHARTIO

Sold GE Equipment Data

GE Asset Resale Values



Average Original Price of Assets Listed

Average Depreciation

\$969,492.37

801,202.00 -96.41%

Average Percent of Original Value

5%

On average, assets were resold for 5% of their original value

Average BBV

\$49,235.29

Difference in BBV and Final Win

\$34,375.06 -30.18%

Average Final Win

\$34,834.87

Hospitals

Name	Seller	City	State
1.5T Excite 4Ch Electronics*			
1.5T HD (12x) 8Ch Electronics			
1.5T HD23 16Ch Electronics Set			
1.5T HDxt Twinspeed 8 Channel Electronics Only			
2004 Infinia II w/ 3/8"			

Copy of iDX CHARTIO

3.0T HDxT		Alabama
GE 1.5T HDxT 8Ch Electronics		
GE Infinia II Hawkeye with 3/8"		Vermont
GE Seno Essential		Nevada
Innova 3100 Unity		Mississippi
Innova 3131 Biplane		Tennessee
Innova 4100 Unity		Illinois
Lightspeed RT16		Indiana
Lightspeed VCT64 Sherlock		Virginia

Locations of Sellers



Number of Sellers (Hospitals)

22

out of 23 sales, there were 22 distinct hospitals

Average De Install Notice

40.18 days

Number of Buyers

5

Out of 23 sales, there were 5 distinct buyers

Effects of Descriptions for Re-sale Value

Name	Details Provided For Buyer
1.5T HDxt with CVI Magnet	P9334UA GP FLEX ASSY2138300-19 1.5T SYSTEM CABINET2144093-6 3T CRM Coil, Gray Cart, Cradle2208999 CRM RF COIL AND CASE2208999 CRM RF COIL AN
Lightspeed RT16	None
1.5T HDxt Electronics Only	8 CHANNEL CARDIAC ARRAY8 CHANNEL CARDIAC ARRAY1.5T 8 CHANNEL NV ARRAY1.5T SPLIT HEAD COIL/PHANTOM COLLECTUSAI 8CH BODY ARRAY COIL, 1.5TUSAI 8C
Innova 3131 Biplane	
GE 1.5T HDxT 8Ch Electronics	
Lightspeed VCT64 Sherlock	
Innova 4100 Angio (Unity)	
2006 Infinia II w/ 3/8"	
1.5T HD23 16Ch Electronics Set	

Copy of iDX CHARTIO

1.5T HD (12x) 8Ch Electronics

Innova 4100 Unity

GE Lightspeed 16 HP60

View all 23 rows and 3 column

Percent of Original Value with Description

15.82% of original value

On average when an asset has an adequate description along with it, it gets about 12% more of its original value

Machines without Descriptions

3.38% of original value

Machines with no description on their listing receive far less than their original value

Page 3 of 3